

कार्यालय कार्यपालन यंत्री
लोक निर्माण विभाग (भ./स.)संभाग क्र.1 रीवा (म.प्र.)

Web site :www.mp.gov.in/pwmp

email :-eepwd 1 rewa@mp.nic.in

Phone No.07662-256858

पत्र क्र.९६३४/तक./2024-25

रीवा,दिनांक 17/01/2024

प्रति,

✓ प्राचार्य,
गुरुकुल पूर्व माध्यमिक विद्यालय
खैरा-रोड चौरहटा,
जिला-रीवा (म.प्र.)


विषय :- गुरुकुल पूर्व माध्यमिक विद्यालय भवन का सुरक्षा प्रमाण पत्र बावत।

संदर्भ :- आपका पत्र 850 /GPMC /2023-24 /रीवा,दिनांक 21/11/2023

उपरोक्त विषयांतर्गत संदर्भित पत्र के तारतम्य में गुरुकुल पूर्व माध्यमिक विद्यालय भवन का सुरक्षा संबंधी प्रमाण पत्र प्रदाय हेतु अनुरोध किया गया है। भवन का मौके से निरीक्षण कर प्रतिवेदन देने हेतु अनुविभागीय अधिकारी लोक निर्माण विभाग (भ./स.)उपसंभाग क्र.1 रीवा को दिनांक 13/12/2023 द्वारा लेख किया गया है। अनुविभागीय अधिकारी लोक निर्माण विभाग (भ./स.) उपसंभाग क्र.1 रीवा एवं उपयंत्री द्वारा दिनांक 08/01/2024 को संयुक्त रूप से विषयांकित भवन का सुरक्षा संबंधी निरीक्षण कर प्रतिवेदन इस कार्यालय को पत्र क्र 993/तक./2024 रीवा,दिनांक 09/01/2024 द्वारा प्राप्त हुआ है।

अतः अनुविभागीय अधिकारी से प्राप्त भवन सुरक्षा प्रमाण पत्र प्रतिहस्ताक्षरित कर आपकी ओर अग्रेषित है।

सहपत्र :-भवन का सुरक्षा प्रमाण पत्र।


कार्यपालन यंत्री
लोक निर्माण विभाग (भ./स.)
संभाग क्र. 1 रीवा (म.प्र.)

OFFICE OF THE EXECUTIVE ENGINEER P.W.D. (B./R.) DIVISION NO.1

REWA (M.P.)

Website: www.mp.gov.in/pwdmp

E- mail- eepwd 1 rewa@mp.nic.in

Phone – 07662 -256858

FITNESS CERTIFICATE

To be filled by the Inspecting Officer

1. Name of the officer : M.K. Dwivedi Divisional Officer P.W.D. (B./R.) Division NO.1 Rewa (M.P.)
2. Name of the School : Gurukul, purv Madhyamik Vidyalaya Rewa (M.P.)
3. Location with name of education District/Sub. District: Khaira Road Chorahata, Rewa, Distt, Rewa (M.P.) 486001
4. Classification of Building as specified in column 4 of the application for fitness certificate and size:
 1. 2043 SQM Tripal Stori (G+2) Built Up Area (Year-2003)
- 5- Period for which the certificate is issued :2024-25
- 6- nature of defects, if any :

a) Foundation and basement:	Not Applicable
b) Superstructure:	Not Applicable
c) Doors and windows:	Not Applicable
d) Wood work wrought and put up :	Not Applicable
e) Roof :	Not Applicable
f) Flooring :	Not Applicable
g) Miscellaneous (Cracks, etc.):	Not Applicable
- 7- any major defects noticed which will render the building unsafe in any manner : No
- 8- Whether maintenance works have been done properly : Yes
- 9- whether the structure is sound or not for conducting classes : Building is sound and safe
Note: 1. the stability of the structure should be examined also with reference to location. altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

Certified that the school building was inspected by me on Dated 08/01/2024 and found to be fit to conduct classes, for the period 2024-25 for the reasons stated above.

Place : Rewa

Date : 08/01/2024



EXECUTIVE ENGINEER

P.W.D.(B./R.) DIVISION NO.1

REWA (M.P.)

Rewa Dated 17/01/2024


Entd. No 6630 /T.S./2024-25

Copy forwarded to :-

✓ Manager,

Guruku purv Madhyamik Vidyalaya

Rewa (M.P.)



EXECUTIVE ENGINEER
P.W.D.(B./R.) DIVISION NO. 1
REWA (M.P.)