

PANCHAYAT SAMITI HURDA DIST. BHILWARA(RAJ)

क्रमांक 1528

दिनांक 01/02/2024

BUILDING SAFETY CERTIFICATE

I do hereby certify that the Zinc Vidyalaya, Hurda School building is inspected by me and has been full fill sufficient parameters of building safety to my satisfaction. The condition of the building is fine.

JUNIOR ENGINEER

PANCHAYAT SAMITI, HURDA



क्रमांक - 1528

CHECK-LIST FOR INSPECTION OF THE SCHOOL BUILDING

Name of the School: Zinc Vidyalaya, Hurda Dist. Bhilwara (Ra)

Date of Inspection: 29/01/2024

Detail of item wise inspection for Building Safety

1. Building:-

I. Walls	No any Leakage/Dampness
II. Floors	No any Leakage/Dampness
III. Roofs	No any Leakage/Dampness
IV. Ceiling	No any Leakage/Dampness

2. Service:-

I. Rain Water Pipe	No any Leakage
II. Sewer Pipe	No any Leakage
III. Water Pipe	No any Leakage
IV. Fire Safety Equipment Sufficient Quantity and Working Properly	
V. Fire extinguisher List	
i. RA/Zinc /School/08	
ii. RA/Zinc/School/09	
iii. RA/Zinc/School/10	
iv. RA/ Zinc/School/11	
v. RA/Zinc/School/12	

3. Whole the systems working Leak proof.

4. Septic tank, sock pit and outside drain are working properly satisfactorily.

5. Whole the building safety parameter fully full fill and building is good condition, maintenance properly.

JUNIOR ENGINEER
उपाध्यक्ष
PANCHAYAT SAMITHI, HURDA
सहायक अभियंता
पंच.स. हुर्दा (भीलवाड़ा)

